## Platfor<u>m</u> W (h (d $\leq$ rawers

## Instructions for Platform Bed with Drawers

- attach both side rails (C) to it using (4) 5" lag bolts (H) and (4) washers (J). Do not tighten bolts completely. 1. Set headboard (A) upright on floor and 2. Slide (4) washers over (4) 4" lag bolts (I)
- and attach foot rail (B) to side rails. Do not tighten bolts completely.
- 4. With the bottoms of slats flush with the 3. Lay (3) slats (F) inside of side rails 8" in from each end of side rails and one in the center.
- to (3) slats and then to side rails using (24) 1-1/4" screws (L). bottoms of side rails, attach (6) brackets (K) screws (L).
- Now tighten all (8) lag bolts.
- Turn platform up on its side.
- Lay out (2) bunk drawer units (D) parallel floor.
- end panel (E) are flush with front corners of drawer units. Spread drawer units so that ends of base
- 9. Attach (2) base end panels to drawer units using (16) 1-1/4" screws (L).
- headboard overhangs the base assembly. outside edge of base end panel. face of the headboard should be flush with 10. Lay platform down across base so that the
- on each side. up with top front rail of each bunk drawer unit into holes provided in slats. drawers using (6) 2-1/2" screws (M) inserted both sides. Attach the platform to the bunk the side rails overhang the platform evenly on Center platform on base assembly so that Holes should line
- of slats then place mattress on top of boards. Lay in (2) bed boards side by side on top

## Parts list

H. 5" lag bolt (4)

l. 4" lag bolt (4)

washer (8)

<u>Hardware</u>

- A. Headboard (1) B. Footboard (1)
- Side rail (2)
- Bunk Drawer Unit (2)
- Base End for Bunk Drawer Unit (2)
- Slat (3)
- Platform bedboard (2) (not shown)

Φ

.. bracket (6) .. 1-1/4" screw (40) M. 2-1/2" screw (6)

 $\bigotimes$ phillips head srewdriver 9/16" socket & ratchet ⓓ